



5	FERRULE	1	BRASS	NICKEL
4	SLEEVE	1	BRASS	NICKEL
3	DIELECTRIC	1	PTFE	NONE
2	PIN	1	BRASS	GOLD
1	BODY	1	BRASS	NICKEL

UNLESS OTHERWISE SPECIFIED
 1. REMOVE ALL BURRS
 2. BREAK ALL CORNERS & EDGES 0.15 MAX.
 3. CHAMFER 1ST & LAST THREADS 25°
 4. DIAMETERS ON COMMON CENTERS TO BE CONCENTRIC WITHIN 0.15
 5. ALL DIMENSIONS ARE

MAJOR DIMENSION
 UNLESS OTHERWISE NOTED TOLERANCES
 0.5-6=±0.2
 6-30=±0.4
 30-120=±0.8
 120-315=±1.0
 ANGLES=±1°



N104

HDF200