



5	FERRULE	1	BRASS	NICKEL	UNLESS OTHERWISE SPECIFIED 1. REMOVE ALL BURRS 2. BREAK ALL CORNERS & EDGES 0.15 MAX. 3. CHAMFER 1ST & LAST THREADS 25° 4. DIAMETERS ON COMMON CENTERS TO BE CONCENTRIC WITH B.Y.T.P. 5. ALL DIMENSIONS ARE	* MAJOR DIMENSIONS UNLESS OTHERWISE NOTED TOLERANCES 0.5-6=±0.2 6-30=±0.4 30-120=±0.8 120-315=±1.0 ANGLES=±1°
4	SLEEVE	1	BRASS	NICKEL		
3	DIELECTRIC	1	PTFE	NONE		
2	PIN	1	BRASS	GOLD		
1	BODY	1	BRASS	NICKEL		



N105

H155